

Morges, 18.01.2012

Technical note N°1/2012

RC44 Class Rule 2012 update

Appendix H – HARDWARE AND FITTINGS

Running rigging specification: add the 2 following points in the table

<i>RUNNING RIGGING SPECIFICATION</i>					
<i>No.</i>	<i>Art.</i>	<i>Rope</i>	<i>Cover</i>	<i>Diameter (minimum)</i>	<i>BL (kg)</i>
51	<i>Forestay strop</i>	<i>Dyneema</i>	<i>May be covered</i>	<i>14mm</i>	<i>10830</i>
52	<i>Runner strops</i>	<i>Dyneema</i>	<i>May be covered</i>	<i>10mm</i>	<i>5920</i>

For the item 51 and 52 the minimum diameter applies to the core only.

An updated version of the Appendix H will be published on the RC44 website on the following page: <http://www.rc44.com/teamzone>

Communication of the Technical Committee:

Mast protection patches: following the tests maid with the new mainsail last year, some small impacts on the grove were noticed around the top battens.

Peter Lovas will supply one design patches to all the teams who are willing to glue a protection patches.

The price of a pair of patches is : 60 Euro

Please contact Peter Lovas (regattaserv@gmail.com) if you want to order some patches for Puerto Calero.

For the Technical Committee,

Bertrand Favre